PRE-CERCLA SCREENING ASSESSMENT CHECKLIST/DECISION FORM

This checklist can assist the site investigator during the Pre-CERCLA screening. It will be used to determine whether further steps in the site investigation process are required under CERCLA. Use additional sheets for the narrative.

Madelyn Adams

	(Name / Title)				Date)		
Ohio EPA (937)					35-6456		
(Agency)				(Phor	(Phone)		
	Madel	yn.Adams@epa.ohio.go	v				
		(Email Address)	_				
Site	e Name:	Former Simclar Facility					
Other Names (if any):		Globe Motors, Globe Industries, TRW, Labinal, Lytton					
Site Location:		1784 Stanley Ave					
		(Street)					
		Dayton	Montgomery	ОН	45404 -	1149	
a	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	(City)	(County)	(State)	(Zip+	-4)	
Co	ngressional District	10	_				
Lat	titude:	39.7872	Longitude:	-84.1853	1		
Co	mplete the following o	·hocklist			YES	NO	
1.	Does the site already ap						
2.		e or potential to release?					
3.							
4.	Are there potential targe	ets on-site or within one mile	e of the site?				
5.	adverse environmental of showing no release above	or human health impacts (e.g	strates that there is no potential g., comprehensive remedial inverval action, documentation shows assessment completed)?	stigation equivalent data			
6.	Is some other program a	actively involved with the si	te (i.e., another Federal, State, o	r Tribal program)?			
7.		ucts that are part of the structures?	cture of, and result in exposure v	vithin, residential			
8.			rring substance in its unaltered fa, from a location where it is nat				
9.	Is the release into a pub	lic or private drinking water	supply due to deterioration of the	ne system through			

Checklist Preparer:

7/29/2016

10. Are the hazardous substances potentially released at the site regulated under a statutory exclusion (i.e., petroleum, natural gas, natural gas liquids, synthetic gas usable for fuel, normal application of fertilizer, release located in a workplace, naturally occurring, or regulated by the NRC, UMTRCA, or OSHA)?							
11. Are the hazardous substances potentially released at the site excluded by policy considerations (e.g., deferral to RCRA Corrective Action)?							
Preparer's Recommendation: □ Enter the site into SEMS. Further assessment is recommended. □ The site is not recommended for placement into SEMS.							
Please explain recommendation below:							
DECISION/DISCUSSION/RATIONALE:							
The property overlies the Great Miami Buried Valley Sole-Source Aquifer and is located approximately 0.5 miles from the city of Dayton's Miami well field well head protection area. The Miami well field serves a population of about 141,400.							
U.S. EPA and Ohio EPA became aware of ground water and soil contamination at the property during sampling for the Behr Dayton Thermal Systems VOC Plume Superfund site (Behr) that is side gradient the Simclar property. Behr is a federally designated Superfund site that has an extensive ground water and vapor plume of TCE. In 2007, as part of the remedial investigation for Behr, the area surrounding Behr was investigated and the three monitoring wells on the Simclar property were sampled: TCA was detected at a concentration of 710 ppb (federal MCL is 200 ppb), as well as TCE and PCE at concentrations of 520 ppb and 22 ppb, respectively (MCL for both compounds is 5 ppb).							
In December 2012, Ohio EPA's Site Investigation Field Unit (SIFU) collected grab ground water samples at the site. The highest ground water detections were 302 ppb 1,1,1-TCA, 12.8 ppb PCE, and 237 ppb TCE.							
On September 10, 2012, a Phase I site assessment was submitted by Turn-Key Environmental Consultants to the Ohio EPA. The Phase I site assessment noted three concerns: 1) Potential releases from former plating operations, exterior storage of chemicals and wastes with identified staining/cracks/corroded concrete/storm drains, and confirmed soil and ground water contamination; 2) A former heating oil UST was removed from the property in 1986; soil samples were taken from the base of the excavation and from the excavated soil. However, no closure report was prepared and no lab report is available; 3) The property is 500 feet from a federal Superfund site (Behr). Ground water just south of the Simclar property contains 100 ppb of TCE. Hence, there may be co-mingling of plumes.							
The Phase I site assessment concluded that further investigation was needed to determine: 1) the source and extent of contamination, 2) whether additional areas of contamination exist, and 3) if contamination is migrating off-site.							
Ohio EPA has been working with two identified potentially responsible parties (PRPs) to negotiate orders requiring them to investigate the site and perform any necessary cleanup; however, the PRPs have not been willing to sign up to an order. Consequently, the case was referred to the Ohio Attorney General's Office and negotiations are ongoing.							
The possibility exists for the ground water plume to be migrating offsite and contributing to vapor intrusion in a downgradient residential area.							

Madelyn Adams /
Preparer's Signature:

Date: 11/9/2016

EPA Regional Review and Site Assessment Decision Incident for further action under CERCLA Not a valid site or incident Defer/Refer to: Removal Program State/Tribal Program **RCRA** Brownfields Other: ____ Regional EPA Reviewer: CHRYSTAL BRANTLEY/ Print Name/Signature October 3, 2016 Date